

FIG. 1




FIG. 2




FIG. 3A ORIGINAL IMAGE




FIG. 3B DEFOCUSED IMAGE




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 9A




FIG. 9B




FIG. 9C




FIG. 9D




FIG. 10




FIG. 11




FIG. 12





FIG. 13A



$$CP44 = (C44 + C45 + C54 + C55) / 4$$

FIG. 13B




FIG. 14A

	$\frac{1}{16}$	$\frac{2}{16}$	$\frac{1}{16}$	
	$\frac{2}{16}$	$\frac{4}{16}$	$\frac{2}{16}$	
	$\frac{1}{16}$	$\frac{2}{16}$	$\frac{1}{16}$	

FIG. 14B

$\frac{1}{256}$	$\frac{4}{256}$	$\frac{6}{256}$	$\frac{4}{256}$	$\frac{1}{256}$
$\frac{4}{256}$	$\frac{16}{256}$	$\frac{24}{256}$	$\frac{16}{256}$	$\frac{4}{256}$
$\frac{6}{256}$	$\frac{24}{256}$	$\frac{36}{256}$	$\frac{24}{256}$	$\frac{6}{256}$
$\frac{4}{256}$	$\frac{16}{256}$	$\frac{24}{256}$	$\frac{16}{256}$	$\frac{4}{256}$
$\frac{1}{256}$	$\frac{4}{256}$	$\frac{6}{256}$	$\frac{4}{256}$	$\frac{1}{256}$

FIG. 15




FIG. 16




FIG. 17




FIG. 18A




FIG. 18B




FIG. 18C

